

## SIERRA WIRELESS PRODUCT CHANGE NOTICE

## **OVERVIEW**

DATE ISSUED:	July 16, 2019
ISSUED BY:	AirPrime Product Management
PRODUCTS AFFECTED:	HL7800-M
SKUS AFFECTED:	1104150
BULLETIN:	Discontinuation of HL7800-M SKU
URGENCY:	Normal
EFFECTIVE DATE:	Effective immediately
FOR DISTRIBUTION TO:	All distributors and customers

# **Summary**

The affected HL7800-M SKUs will be discontinued and replaced by a new SKU.

# **Details of Change**

#### **Affected SKU**

## Replaced By

1104150 (HL7800-M, firmware v1.7.15.0)

1104648 (HL7800-M, firmware v3.7.2.3)

SKU 1104648 is a direct replacement of the affected SKUs. It ships with v3.7.2.3 firmware which provide improvements over the affected SKUs. For a list of changes, please download the firmware release history from the <u>Source</u>.

## **Effective Dates**

This change is effective immediately. The replacement SKU is now in volume production.

## More information

For more information please contact your Sierra Wireless sales representative.