

## **Product Change Notification**

# PCN No: DAS-16-0609-CCB-0211

RFX8053 change in package thickness and datasheet change for EVM MCS9.

Notification Date: 03/07/2017

Notification Period: 30 days

#### Proposed First Ship Date for Change: 04/06/2017

Qualification Data Availability Date: 06/10/2016 Sample Availability Date: Not Applicable Last Date of Manufacture of Unchanged Product: 04/06/2016

#### Dear Valued Skyworks Customer:

Please be advised that Skyworks Solutions Inc. is introducing the following product change(s):

## Description and Scope of Change

Change of package thickness from 0.4 mm max to 0.45 mm max, for improved manufacturability. Datasheet change for the minimum power specification in the datasheet for EVM MCS9 from 16.5dBm static EVM to 14.5dBm dynamic EVM

## Products Affected

RFX8053

## Method for Identifying Changed Product

Full product change traceability is maintained by: lot code

#### Reason for Change

Change to package thickness will improved manufacturability. Datasheet does not reflect performance of the part, requiring change.

## Anticipated Impact on Form, Fit Function, Reliability, Quality or Safety

No customer impact is anticipated with this change; there is no change to form, function, reliability, quality or safety. There is a change to fit for the package thickness change.

#### **Qualification Plan Summary**

Refer to qualification report for package thickness change. Datasheet change does not include any additional change to part.

#### Launch Plan

Upon customer notification.

Please contact your Skyworks customer service representative with any questions or comments regarding this change. If you are unsure whom to contact, please email Skyworks Change Management at <u>Skyworks.CCB@Skyworksinc.com</u>.

## Skyworks Solutions, Inc.

20 Sylvan Boad, Woburn, MA 01801 USA: (781) 376-3000 • Asia: 886 2 2735 0399 Europe: 33 (0)1 43548540 • Fax: (781) 376-3300 On the Web: <u>www.skyworksinc.com</u>