u·p·t·o·d·a·t·e Newsletter 🐼 DK

March 18, 2022

## PTN Withdrawal of leaded VHF chokes B8213

For the production of EPCOS VHF chokes of the B8213\* series, iron powder cores from a supplier that obtains the powder from Russia are used. Due to current events, however, there is no longer any supply to us in the meantime. Alternative sources of supply are unfortunately not available despite intensive efforts on our part.

Since the cause is beyond the control of TDK and the effects cannot be foreseen in time, the following leaded EPCOS VHF chokes will be withdrawn **with immediate effect** without observing the usual periods for notification.

Ordering code	Substitute type
B82131A5151M000	-
B82131A5152M000	-
B82131A5202M000	-
B82131A5301M000	-
B82131A5302M000	-
B82131A5401M000	-
B82131A5401M009	-
B82131A5402M000	-
B82131A5701M000	-
B82131C5152M000	-
B82132A5151M000	-
B82132A5152M000	-
B82132A5202M000	-
B82132A5301M000	-
B82132A5302M000	-
B82132A5401M000	-
B82132A5402M000	-
B82132A5701M000	-
B82133A5151M000	-
B82133A5152M000	-
B82133A5202M000	-
B82133A5301M000	-
B82133A5302M000	-
B82133A5401M000	-
B82133A5402M000	-
B82133A5701M000	-

## Affected products

## **TDK Electronics AG**

Rosenheimer Strasse 141 e, 81671 Munich · Post: P.O.Box 80 17 09, 81617 Munich, Germany Headquarters: Munich · Commercial register of the local court (Amtsgericht): Munich HRB 127250 Chairman of the Supervisory Board: Dr. Werner Faber Management Board: Joachim Zichlarz, Chairman · Joachim Thiele · Dr. Werner Lohwasser www.tdk-electronics.tdk.com Inductors Internal / External u·p·t·o·d·a·t·e Newsletter

March 18, 2022

P	
B82134A5151M000	-
B82134A5152M000	-
B82134A5202M000	-
B82134A5301M000	-
B82134A5302M000	-
B82134A5401M000	-
B82134A5701M000	-

TDK will make every effort to still service orders that have already been confirmed.

For alternative parts please contact your regional sales contact.

Contact Susanne Döring, MAG IN PM, Munich

Customers are asked to address inquiries directly to their sales contacts.