



Product Change Notification

TE Connectivity

Product Change Notification: E-15-003129

PCN Date: 04-MAR-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
CPC connectors with 4-40 threaded bushings

Description of Changes
Add a note to the production drawing stating the 4-40 bushings are to be assembled from the mating side of the housing flange during the assembly operation in the TE manufacturing plant.

Reason for Changes:
Product Improvement. The note is required to ensure the bushings are assembled in a consistent manner. Although all of the part numbers listed on this notice will receive a revision change, the only parts which contain bushings and may be impacted by the note change are the following: 206934-9, 1-206934-3, 1-206934-4, 1-206934-7, 2-206934-7, 2-206934-8

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	30-MAY-2015
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-206934-1	NO						
1-206934-7	NO						
206934-5	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-206934-7	NO						
206934-5	NO						