



Product Change Notification

TE Connectivity

Product Change Notification: E-16-010359

PCN Date: 25-JUL-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
 DEUTSCH DT, DRB, DTM, DTP, DTV, DTMH Series Connectors

Description of Changes
 The Industrial & Commercial Transportation (ICT) business unit of TE Connectivity (TEC) intends to implement a supplier and a process change to the secondary wedge locks. The current process is using pre-colored raw material, the new raw material is going to be colored at the molding press. PPAP package will be offered by customer request once a sufficient inventory bank is built to prevent any delay. Product drawings are not affected.

CURRENT AND NEW COLOR

Current Color	New Color

Reason for Changes:
 Product Improvement. Dear Customer, we inform you of this process change as part of our aggressive continuous improvement efforts. The current supplier is a single source supplier and will no longer supply pre-colored raw material. To address the supply restrictions TEC is implementing supplier and process change. The current and the new raw material is PBT 30GF, however the new raw material will be colored at the molding press. The change will be managed by TEC TS16949 quality procedures. The change does not affect the fit, form and function of the connectors. The change has been validated with manufacturing and laboratory testing. An internal release based on our specifications will be executed before any parts are delivered. **IMPORTANT:** The current and previous revisions of these parts can be used interchangeably in the field. This change is being phased-in gradually and the previous revision can remain stocked until use.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	15-OCT-2016
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W12P	NO			"ZPF000000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF000000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF000000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$W12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF000000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L"			
W2S	NO			"ZPF000000000131424"			
W2S-P012	NO			"ZPF000000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$W2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M"			
W3P	NO			"ZPF000000000131434", "W3P-AS", "W3P-LS", "\$W3P", "W3P-L"			
W3P-1939	NO			"ZPF000000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF000000000131437"			
W3S-1939-P012	NO			"ZPF000000000131438", "W3S-1939-P012-AS", "W3S-1939-P012-MS", "W3S-1939-P012-M", "7-1899794-6"			
W3S-P012	NO			"ZPF000000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$W3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF000000000131440", "W4P-AS"			
W4S-P012	NO			"ZPF000000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			
W4S-ZZ	NO			"W4S", "ZPF000000000131445", "W4S-AS"			
W6P	NO			"ZPF000000000131455", "W6P-AS", "\$W6P"			
W6S	NO			"ZPF000000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF000000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			
W8P	NO			"ZPF000000000131459"			
W8S	NO			"ZPF000000000131460", "6-1899776-4"			
W8S-P012	NO			"ZPF000000000131461", "W8S-P012-AS", "W8S-P012-LD", "W8S-P012-LS", "W8S-P012-MS", "W8S-P012-L", "W8S-P012-M"			
WB-48PA	NO			"ZPF000000000131488", "WB-48PA-AS", "WB-48PA-LD", "WB-48PA-L"			
WB-48SA	NO			"ZPF000000000131492", "WB-48SA-AS", "WB-48SA-LD", "WB-48SA-L"			
WB-51PAL	NO			"ZPF000000000131504", "WB-51PAL-LD", "WB-51PAL-LS", "WB-51PAL-L"			
WB-51PAR	NO			"ZPF000000000131505", "WB-51PAR-LD", "WB-51PAR-LS", "WB-51PAR-L"			
WB-51SAL	NO			"ZPF000000000138179", "WB-51SAL-LS", "WB-51SAL-L"			
WB-51SAR	NO			"ZPF000000000131507", "WB-51SAR-LS", "WB-51SAR-L"			
WB-60PA	NO			"ZPF000000000131496"			
WB-60SA	NO			"ZPF000000000131500"			
WB-64PA	NO			"ZPF000000000145889"			
WB-64SA	NO			"ZPF000000000145888", "WB-64SA-LS", "WB-64SA-L"			
WM-12P	NO			"ZPF000000000131479", "WM-12P-MS", "WM-12P-M"			
WM-12S	NO			"ZPF000000000131480", "WM-12S-AS", "WM-12S-LS", "WM-12S-L"			
WM-2P	NO			"ZPF000000000131465", "WM-2P-AS"			
WM-2PB	NO			"ZPF000000000131467"			
WM-2S	NO			"ZPF000000000131468", "WM-2S-AS"			
WM-2SB	NO			"ZPF000000000131470"			
WM-3P	NO			"ZPF000000000131471"			
WM-3S	NO			"ZPF000000000131472", "WM-3S-AS"			
WM-4P	NO			"ZPF000000000113018", "ZPF000000000131473", "WM 4P"			
WM-4S	NO			"ZPF000000000113019", "ZPF000000000131474", "WM 4S"			
WM-6P	NO			"ZPF000000000131475"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
WM-6S	NO			"ZPF000000000131476", "2231457-1"			
WM-8P	NO			"ZPF000000000131477", "WM-8P-AS"			
WM-8S	NO			"ZPF000000000131478"			
WP-2P	NO			"ZPF000000000131482", "WP-2P-AS"			
WP-2S	NO			"ZPF000000000131483"			
WP-4P	NO			"ZPF000000000131484"			
WP-4S	NO			"ZPF000000000131485", "WP-4S-LD", "WP-4S-LS", "WP-4S-L"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W12P	NO			"ZPF000000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF000000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF000000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$W12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF000000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L"			
W2S	NO			"ZPF000000000131424"			
W2S-P012	NO			"ZPF000000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$W2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M"			
W3P	NO			"ZPF000000000131434", "W3P-AS", "W3P-LS", "\$W3P", "W3P-L"			
W3P-1939	NO			"ZPF000000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF000000000131437"			
W3S-1939-P012	NO			"ZPF000000000131438", "W3S-1939-P012-AS", "W3S-1939-P012-MS", "W3S-1939-P012-M", "7-1899794-6"			
W3S-P012	NO			"ZPF000000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$W3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF000000000131440", "W4P-AS"			
W4S-P012	NO			"ZPF000000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			
W4S-ZZ	NO			"W4S", "ZPF000000000131445", "W4S-AS"			
W6P	NO			"ZPF000000000131455", "W6P-AS", "\$W6P"			
W6S	NO			"ZPF000000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF000000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			
W8P	NO			"ZPF000000000131459"			
W8S	NO			"ZPF000000000131460", "6-1899776-4"			
W8S-P012	NO			"ZPF000000000131461", "W8S-P012-AS", "W8S-P012-LD", "W8S-P012-LS", "W8S-P012-MS", "W8S-P012-L", "W8S-P012-M"			
WB-48PA	NO			"ZPF000000000131488", "WB-48PA-AS", "WB-48PA-LD", "WB-48PA-L"			
WB-48SA	NO			"ZPF000000000131492", "WB-48SA-AS", "WB-48SA-LD", "WB-48SA-L"			
WB-51PAL	NO			"ZPF000000000131504", "WB-51PAL-LD", "WB-51PAL-LS", "WB-51PAL-L"			
WB-51PAR	NO			"ZPF000000000131505", "WB-51PAR-LD", "WB-51PAR-LS", "WB-51PAR-L"			
WB-51SAL	NO			"ZPF000000000138179", "WB-51SAL-LS", "WB-51SAL-L"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
WB-51SAR	NO			"ZPF000000000131507", "WB-51SAR-LS", "WB-51SAR-L"			
WB-60PA	NO			"ZPF000000000131496"			
WB-60SA	NO			"ZPF000000000131500"			
WB-64PA	NO			"ZPF000000000145889"			
WB-64SA	NO			"ZPF000000000145888", "WB-64SA-LS", "WB-64SA-L"			
WM-12P	NO			"ZPF000000000131479", "WM-12P-MS", "WM-12P-M"			
WM-12S	NO			"ZPF000000000131480", "WM-12S-AS", "WM-12S-LS", "WM-12S-L"			
WM-2P	NO			"ZPF000000000131465", "WM-2P-AS"			
WM-2PB	NO			"ZPF000000000131467"			
WM-2S	NO			"ZPF000000000131468", "WM-2S-AS"			
WM-2SB	NO			"ZPF000000000131470"			
WM-3P	NO			"ZPF000000000131471"			
WM-3S	NO			"ZPF000000000131472", "WM-3S-AS"			
WM-4P	NO			"ZPF000000000113018", "ZPF000000000131473", "WM 4P"			
WM-4S	NO			"ZPF000000000113019", "ZPF000000000131474", "WM 4S"			
WM-6P	NO			"ZPF000000000131475"			
WM-6S	NO			"ZPF000000000131476", "2231457-1"			
WM-8P	NO			"ZPF000000000131477", "WM-8P-AS"			
WM-8S	NO			"ZPF000000000131478"			
WP-2P	NO			"ZPF000000000131482", "WP-2P-AS"			
WP-2S	NO			"ZPF000000000131483"			
WP-4P	NO			"ZPF000000000131484"			
WP-4S	NO			"ZPF000000000131485", "WP-4S-LD", "WP-4S-LS", "WP-4S-L"			