

TE Connectivity

Product Change Notification: E-17-009160

PCN Date: 02-JUL-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Ultraslim sockets series: 2-821949-5, 2-822064-5, 2-822114-4, 821939-1, 821942-1, 821949-5, 822064-4, 822115-3, 822115-4

Description of Changes

This change is considered by TE Connectivity as a; . Location of change, see The following part numbers are being obsoleted (obsolete status). A last time buy opportunity is provided as per the dates stated thereafter. Please note that new conditions may apply, please contact your local customer sales representative for a quotation

Reason for Changes:						
Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter.						
Estimated Dates:						
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):					
28-SEP-2017						
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):					
28-OCT-2017	No Mixed Shipments					

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
182885-1	YES					
<u>2-821949-5</u>	YES					
2-822064-5	YES					
2-822114-4	YES					
<u>821939-1</u>	YES					
821942-1	YES					
<u>821949-5</u>	YES			2-821949-5		RoHS compliant part
822064-4	YES					
<u>822115-3</u>	YES					
822115-4	YES		"28-20040-00"			