

TE Connectivity

Product Change Notification: E-20-006124 PCN Date: 28-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Solder devices as per attached list of parts.

Description of Changes
Flux change in solder preform from ROL0 flux to ROM1 flux , both are in accordance with ANSI J-STD-004B

Reason for Changes:

Product Improvement. Certain products within our Devices product line have been manufactured with a ROLO flux instead of ROM1 flux as required under applicable specifications (including TE and external agency specifications). ROLO flux is being replaced with ROM1 to comply with specifications Although test data demonstrates ROLO flux meets performance requirements, TE is changing to a ROM1 flux that complies with relevent specifications, including applicable MIL specifications as required. Some customers may receive mixed shipments for a few weeks as we switch flux materials.

Estimated Dates:						
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):					
	29-MAY-2020					
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):					
	30-JUN-2020					

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
156869-000	NO			"8-1191133-5", "SGRS-2"			
<u>294297-000</u>	NO			"9-1192229-2", "SGRS-3"			
307416N001	NO			"4-1192328-8", "D-150- 1010CS821"			
322299-000	NO			"1192440-1", "SGRP-1"			
358733-000	NO			"7-1192691-4", "CWT- 3801"			
359287N001	NO			"5-1192695-3", "D-150- 1008CS821"			
528006N001	NO			"9-1194147-4", "D-150- 1006CS821"			
610147N001	NO			"7-1194824-5", "D-150- 1013CS821"			
667353-000	NO			"1-1195256-5", "CWT- 1501"			
919829-000	NO			"8-1197137-9", "SGRP-3"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>156869-000</u>	NO			"8-1191133-5", "SGRS-2"			
307416N001	NO			"4-1192328-8", "D-150- 1010CS821"			
322299-000	NO			"1192440-1", "SGRP-1"			
358733-000	NO			"7-1192691-4", "CWT- 3801"			
359287N001	NO			"5-1192695-3", "D-150- 1008CS821"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
528006N001	NO			"9-1194147-4", "D-150-			
				1006CS821"			
610147N001	NO	NO		"7-1194824-5", "D-150-			
610147N001	NO			1013CS821"			
667353-000	NO	NO	"1-1195256-5", "CWT-				
				1501"			
919829-000	NO			"8-1197137-9", "SGRP-3"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
156869-000	NO			"8-1191133-5", "SGRS-2"			
307416N001	NO			"4-1192328-8", "D-150- 1010CS821"			
322299-000	NO			"1192440-1", "SGRP-1"			
358733-000	NO			"7-1192691-4", "CWT- 3801"			
359287N001	NO			"5-1192695-3", "D-150- 1008CS821"			
528006N001	NO			"9-1194147-4", "D-150- 1006CS821"			
510147N001	NO			"7-1194824-5", "D-150- 1013CS821"			
667353-000	NO			"1-1195256-5", "CWT- 1501"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
294297-	NO			"9-1192229-2",			
000	NO			"SGRS-3"			