

TE Connectivity

Product Change Notification: E-20-017921 PCN Date: 28-DEC-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

DEUTSCH DT and DTM Series Tooling replacement in final assembly process.

Description of Changes

The Industrial and Commercial Transportation business unit of TE Connectivity is replacing the final assembly tooling for a new one for the part numbers listed below. These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved. Product drawings are not affected.

Reason for Changes:

Dear Customer, we hereby inform you of this change. The new tooling is necessary to improve our assembly process. The added tooling does not impact product performance. IMPORTANT: No fit, form or function change. Shipments before this new tooling and after may be mixed.

Estimated Dates:

Estimated Dates:		
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):	
	31-DEC-2020	
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):	
	03-JUN-2022	

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DT04-6P- EP14	NO			"ZPF000000000141316"			
DT06-12S- B031	NO						
DT06-12SA- C017	NO						
DT06-2S- C017	NO						
DT06-3S- CE14	NO						
DT06-3S- CL08	NO						
DT06-3S- EP09	NO						
DT06-3S- EP10	NO						
DT06-3S- P006	NO			"6-1899776-0"			
DT06-3S- P032	NO						
DT06-3S- PE01	NO						
DTM04-2P- EP10	NO			"ZPF000000000130136", "DTM04-2P-EP10- AS"			
DTM04-2P- P006	NO			"ZPF00000000130137"			
DTM06-2S- EP10	NO			"ZPF000000000130140", "DTM06-2S-EP10- AS", "DTM06-2S-EP10-LS", "DTM06-2S- EP10-L"			
DTM06-2S- P006	NO			"ZPF000000000130146", "DTM06-2S-P006- LS", "DTM06-2S-P006-L"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DT04-6P- EP14	NO			"ZPF00000000141316"			
DT06- 12SA-C017	NO						
DT06-2S- C017	NO						
DT06-3S- EP09	NO						
DT06-3S- P032	NO						
DT06-3S- PE01	NO						
DTM04- 2P-EP10	NO			"ZPF000000000130136", "DTM04-2P-EP10- AS"			
DTM04- 2P-P006	NO			"ZPF00000000130137"			
DTM06- 2S-EP10	NO			"ZPF000000000130140", "DTM06-2S-EP10- AS", "DTM06-2S-EP10-LS", "DTM06-2S- EP10-L"			
DTM06- 2S-P006	NO			"ZPF000000000130146", "DTM06-2S-P006- LS", "DTM06-2S-P006-L"			

Part Number(s) being Modified:

	are realised (5) being mounted.									
Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference			
DT06-12SA- C017	NO									
DT06-2S- C017	NO									
DT06-3S- EP09	NO									
DT06-3S- P032	NO									
DTM04-2P- EP10	NO			"ZPF000000000130136", "DTM04- 2P-EP10-AS"						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DT06-12S- B031	NO						
DT06-3S- CE14	NO						
DT06-3S- CL08	NO						
DT06-3S- EP09	NO						
	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DT06-3S-							
EP10							
DT06-3S- P006	NO			"6-1899776-0"			
DTM04- 2P-EP10	NO			"ZPF000000000130136", "DTM04-2P-EP10- AS"			
DTM04- 2P-P006	NO			"ZPF00000000130137"			
DTM06- 2S-EP10	NO			"ZPF000000000130140", "DTM06-2S-EP10- AS", "DTM06-2S-EP10-LS", "DTM06-2S- EP10-L"			
DTM06- 2S-P006	NO			"ZPF000000000130146", "DTM06-2S-P006- LS", "DTM06-2S-P006-L"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DT06-12S- B031	NO						
DT06-3S- CE14	NO						
DT06-3S- CL08	NO						
DT06-3S- EP09	NO						
DT06-3S- EP10	NO						
DT06-3S- P006	NO			"6-1899776-0"			
DTM04- 2P-EP10	NO			"ZPF000000000130136", "DTM04-2P-EP10- AS"			
DTM04- 2P-P006	NO			"ZPF00000000130137"			
DTM06- 2S-EP10	NO			"ZPF000000000130140", "DTM06-2S-EP10- AS", "DTM06-2S-EP10-LS", "DTM06-2S- EP10-L"			
DTM06- 2S-P006	NO			"ZPF000000000130146", "DTM06-2S-P006- LS", "DTM06-2S-P006-L"			