

# **TE Connectivity**

Product Change Notification: E-21-004018 PCN Date: 13-APR-21

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
COPALUM Lite 1/0 Terminals

### Description of Changes

Changing the lubricant on the terminals to one with a UV marking. This will insure that the vision system will be able to detect the presence of the lubricant 100% of the time. The previous lubricant did not have a great enough contrast. Boeing has approved of this change 4-1-2021 per Dan Coates

Reason for Changes:			
Product Improvement.			
Estimated Dates:			
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):		
	30-APR-2021		
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):		
	No Mixed Shipments		

### Part Number(s) being Modified:

Part Number	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
2102580-1	NO						

## Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
2102580-1	NO						

#### Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Numbe		Drawing	Number	Number(s)	Number	Number(s)	Difference
2102580-	<u>1</u> NO						