

## Product Change Notification

## TE Connectivity

Product Change Notification: P-14-010626

## PCN Date: 02-OCT-14

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:				
D2n, V23105, all part numbers of IPC D830				
	-			

Description of Changes	
Clarification of the UL file	

Reason for Changes:					
Document clarification. Dear customer because of administrative deviations at our D2N UL file we are not allowed to print UL marking on the relays until this issue is solved. We undertake all necessary work to keep this time period as short as possible. The relays are still same as in past and unchanged. Sincerely TE					
Estimated Dates:					
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):				
	02-OCT-2014				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	No Mixed Shipments				

## Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1-1393793-</u> 1	NO		"V23105A5407A201"			
<u>1-1393793-</u> <u>3</u>	NO		"V23105A5476A201"			
<u>1-1393793-</u> <u>6</u>	NO		"V23105A5501A201"			
<u>1-1393793-</u> 9	NO		"V23105A5503A201"			
1393793-3	NO		"V23105A5307A201"			
<u>1393793-5</u>	NO		"V23105A5308A201"			
<u>1393793-6</u>	NO		"V23105A5401A201"			
<u>1393793-8</u>	NO		"V23105A5403A201"			
<u>1393793-9</u>	NO		"V23105A5405A201"			
<u>2-1393793-</u> 1	NO		"V23105A5505A201"			
<u>8-1393792-</u> 5	NO		"V23105A5001A201"			
<u>8-1393792-</u> <u>8</u>	NO		"V23105A5003A201"			
<u>9-1393792-</u> <u>0</u>	NO		"V23105A5005A201"			
<u>9-1393792-</u> <u>3</u>	NO		"V23105A5301A201"			
<u>9-1393792-</u> <u>7</u>	NO		"V23105A5303A201"			
<u>9-1393792-</u> <u>9</u>	NO		"V23105A5305A201"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>8-</u> 1393792-5	NO			"V23105A5001A201"			
<u>9-</u> 1393792-0	NO			"V23105A5005A201"			