



# TE Connectivity

Product Change Notification: P-16-013168 PCN Date: 19-JUN-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:	
Eurocard Connector, Assembly	

Description of Changes

Change the part number and DC print from laser to laser or ink optional. For some parts, also change the print area. see attached document for detail.

Other attachments:

part change details

Reason for Changes:			
Document clarification.Our plant now has issues to print with la	ser because the laser equipment was damaged		
Estimated Dates:			
Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only):			
	21-SEP-2016		
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):		
	No Mixed Shipments		

# Part Number(s) being Modified:

Part Number	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of
Part Number	per PCN	Drawing	Number	Alias Fart Nulliber(s)	Number	Part Number(s)	Difference
2-1393659-6	NO			"V42254B1201R480"			
3-1393659-9	NO			"V42254B1202R480"			
6-1393644-3	NO			"V42254B1200B610"			
6-1393644-6	NO			"V42254B1200B640"			
6-1393644-9	NO			"V42254B1200C300"			
7-1393644-1	NO			"V42254B1200C310"			
8-1393644-0	NO			"V42254B1200C480"			
8-1393644-3	NO			"V42254B1200C910"			
9-1393644-1	NO			"AMP-9-1393644-1", "F02303-000", "V42254B1200C960"			
9-1393644-4	NO			"A14257-000", "AMP-9-1393644-4", "V42254B1200C963"			

### Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part Number	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number	(s)	Number	Number(s)	Difference
2-1393659-6	NO			"V42254B1201R480	"		

# Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-1393659	1	2.49		"V42254B1201R480"			2
3-1393659	9 NO			"V42254B1202R480"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6-1393644-9	NO			"V42254B1200C300"			
7-1393644-1	NO			"V42254B1200C310"			
8-1393644-3	NO			"V42254B1200C910"			
9-1393644-1	NO			"AMP-9-1393644-1", "F02303-000", "V42254B1200C960"			
9-1393644-4	NO			"A14257-000", "AMP-9-1393644-4", "V42254B1200C963"			

#### Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alica Dart Nursehar(a)	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Alias Part Number(s)	Number	Part Number(s)	Difference
2-1393659-6	NO			"V42254B1201R480"			
3-1393659-9	NO			"V42254B1202R480"			
6-1393644-9	NO			"V42254B1200C300"			
7-1393644-1	NO			"V42254B1200C310"			
8-1393644-3	NO			"V42254B1200C910"			
9-1393644-1	NO			"AMP-9-1393644-1", "F02303-000", "V42254B1200C960"			
9 1393644	NO			"A14257-000", "AMP-9-1393644-4", "V42254B1200C963"			

# Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part Number	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number	(s)	Number	Number(s)	Difference
2-1393659-6	NO			"V42254B1201R480"			
6-1393644-3	NO			"V42254B1200B610"			
6-1393644-6	NO			"V42254B1200B640"			
8-1393644-0	NO			"V42254B1200C480"			

# Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part Number	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number	(s)	Number	Number(s)	Difference
2-1393659-6	NO			"V42254B1201R480"			
6-1393644-3	NO			"V42254B1200B610"			
6-1393644-6	NO			"V42254B1200B640"			
8-1393644-0	NO			"V42254B1200C480"			·