PDN Number: 2012			70707000			PDN Date:		July 7, 2017	
Title:	Discontinuance of the SN75LBC978DL/R								
Customer Contact:			PCN Ma	PCN Manager			Quality Services		
Last date to order:				July 7, 2018 Last date t		o ship: Jan 7, 2019		Jan 7, 2019	
Change Type:			Prod	Product Discontinuance - End Of Life					
Product Discontinuance Notification Details									
Description of Discontinuance:									
Recommended replacements are also offered on some devices as shown in the Product Affected Section. NOTE: There are no samples offered for withdrawn/obsolete products. For samples of any replacement products, please contact your local sales representative.									
Reason for Withdrawal/Discontinuance:									
Supplier is obsoleting the leadframe and demands do not justify new tooling.									
Product Affected:									
_	DEVICES BEING DISCONTINUE			RECOMM	IENDED REPLA PRODUCTS	ACEMENT	R	EPLACEMENT CODES	
SN75LBC978DL			DL	SN7597	6A1DL, SN759	76A2DL		Р	
SN75LBC978DLR			DLR	SN75976	A1DLR, SN759	76A2DLR		Р	

Replacement Notes:

- F = Similar functionality but not equivalent.
- P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.

- Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.
- S = EXACT equivalent in functionality and parametrically to the compared device.

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com