

Product Change Notification

TRINAMIC Motion Control GmbH & Co. KG Waterloohain 5, 22769 Hamburg, Germany

www.trinamic.com

EOL_2021-06-21_ TMC4330_4331_6130

June 21, 2021

Dear Valued Trinamic Customer,

This product discontinuation notice is to inform you that Trinamic will discontinue the following products.

TMC4330A-LA-T TMC4330A-LA-T TMC4330-EVAL

TMC4331A-LA-T TMC4331A-LA-T TMC4331-EVAL

TMC6130-LA TMC6130-LA-T

We will continue to provide support of this products through **June 21, 2022**

Support for these products will be limited to firmware, software, and existing documentation that is available on the corresponding product pages on www.trinamic.com.

Products Affected

Article Name (MPN)	Article Number
TMC4330A-LA	00-0138
TMC4330A-LA-T	00-0138T
TMC4330-EVAL	40-0150
	•
TMC4331A-I A	00-0148

TMC4331A-LA	00-0148
TMC4331A-LA-T	00-0148T
TMC4331-EVAL	40-0080



Product Change Notification

TRINAMIC Motion Control GmbH & Co. KG Waterloohain 5, 22769 Hamburg, Germany

www.trinamic.com

EOL_2021-06-21_ TMC4330_4331_6130

June 21, 2021

TMC6130-LA	00-0115
TMC6130-LA-T	00-0115T

Timing

Effective date for placing last purchase orders until	December 21, 2021
Final shipments until	June 21, 2022

If you have any questions, please reach out to your sales contact.

Classification

This EOL is classified as critical.

Replacement Products

Product Affected (MPN)	Replacement Part (MPN)
TMC4330A-LA	
TMC4330A-LA-T	TMC4361A-LA TMC4361A-LA-T TMC4361A-EVAL
TMC4330-EVAL	
TMC4331A-LA	
TMC4331A-LA-T	
TMC4331-EVAL	
TMC6130-LA TMC6130-LA-T	TMC6140-LA
	TMC6140-LA-T
	TMC6140-EVAL