



June 20, 2022 (Updated from PCN dated December 9, 2021)

Product Change and EOL Notification

Customer: All TTM RF&S Order#: All P/N: See table below Qty Affected: All


Notice of Change(s):

TTM RF&S would like to inform of a change to the 0603 sized components listed in the table below.

Part Number	Part Number
X0060L5050AHF	BD2326L50150AHF
X0060L7575AHF	BD2326L50200AHF
PD2635L5050S2HF	


The drawings below detail the change (see highlighted in yellow).

Previous Mechanical Outline:




^{**.}XX+/-.0X is specific to part number

New Mechanical Outline:









Tel 315.233.5510

Old part numbers with the old mechanical outline are being obsoleted and new part numbers are assigned with the new mechanical outline. There is **no change** in the footprint and **no change** in the functionality and performance of these parts.

See table below.

Old Part Number	New Part Number
X0060L5050AHF	X0060L5050AHF2
X0060L7575AHF	X0060L7575AHF2
PD2635L5050S2HF	PD2635L5050S2HF2
BD2326L50150AHF	BD2326L50150AHF2
BD2326L50200AHF	BD2326L50200AHF2

Justification:

This change has been implemented as part of a continuous process improvement.

Timeline:

Based on open and forecasted orders, we anticipated that stock of the old part numbers will be depleted by mid-2022 and then obsoleted. New part numbers will begin shipping at this time.

To help determine the impact of this change on customer system, samples of parts with the new size can be made available in Q1, 2022.

If you have any questions or need further information, please call me at 1-315-233-5691 or send e-mail to andrew.kempf@ttm.com

Sincerely,
Andrew Kempf
Director of Program Management
TTM Technologies Company
http://www.ttm.com