

Product Change Notification



Product Group: Vishay Dale/February 5, 2020/PCN-DI-00477-2020 Rev 0

QX32P-SW325 Connector Product Obsolescence

DESCRIPTION OF CHANGE: The Vishay Connectors QX32P-SW325 is becoming obsolete, effective

immediately.

CLASSIFICATION OF CHANGE: Product Obsolescence

REASON FOR CHANGE: Vishay no longer has the ability to perform the acceptance testing required.

EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: N/A

PRODUCT CATAGORY: Connectors

PART NUMBERS/SERIES/FAMILIES AFFECTED:

QX32P-SW325

VISHAY BRAND(s): Vishay Dale

TIME SCHEDULE:

Start Shipment Date: N/A Last Time Buy Date: NA Last Time Shipment Date: NA

SAMPLE AVAILABILITY: N/A

PRODUCT IDENTIFICATION: N/A

QUALIFICATION DATA: N/A

This PCN is considered approved, without further notification, unless we receive specific customer concerns or as specified by contract.

ISSUED BY: Doug Lillie, Sr. Product Marketing Manager

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

The Americas

Vishay Intertechnology, Inc 1505 East Highway 50 P. O. Box 180 Yankton, South Dakota 57078

Ph: 1 605-665-9301 Fax: 1 605-665-1627 doug.lillie@vishay.com Europe

Vishay Electronic GmbH Dr.-Felix-Zandman-Platz 1 95100 Selb

Germany

Ph: 49-9287-71-2282 Fax: 49-9287-71-2496 jens.walther@vishay.com Asia

Vishay Asia Pte Ltd. 25 Tampines Street 92 Keppel Building #02-00 Singapore 528877 Ph: +65-788-6668 Fax: +65-788-3383 victor.goh@vishay.com

Vishay Intertechnology, Inc.