$$\label{eq:max-ey} \begin{split} \text{Max-Eyth-Straße 1} & \cdot \text{74638 Waldenburg} \cdot \text{Germany} \\ \text{Tel.} & +49 (0) \, 79 \, 42 \, 945 - 0 \cdot \text{Fax} \\ & +49 (0) \, 79 \, 42 \, 945 - 400 \\ \text{eiSos@we-online.de} \cdot \text{www.we-online.de} \end{split}$$



| Product / Process Change Notification (PCN) | | | | | | | | |
|---|-----------------------------|---|--|--|--|--|--|--|
| PCN #: | PCN_UtRJ45LAN_20201209 | Change Category: | | | | | | |
| Affected Series: | WE-UtRJ45LAN;7499xxx; S1xxx | □ Equipment / Location□ General Data☑ Material | | | | | | |
| PCN Date: | September 09, 2020 | □ Process | | | | | | |
| Effective Date: | December 09, 2020 | ☑ Product Design☐ Shipping / Packaging☐ Supplier☐ Software | | | | | | |
| Contact: | Product Management | Data Sheet Change: | | | | | | |
| Phone: | +49 (0) 7942 - 945 5001 | □ Yes ⊠ No | | | | | | |
| Fax: | +49 (0) 7942 - 945 5179 | Attachment: | | | | | | |
| E-Mail: | pcn.eisos@we-online.com | □ Yes ⊠ No | | | | | | |
| DESCRIPTION AND PURPOSE OF CHANGE: | | | | | | | | |
| To ensure an improved product assembly, Würth Elektronik will change the form of the insert and material of insert and housing to PA66. | | | | | | | | |
| All products with date code 2020-12-09 or later, will be affected by this change. | | | | | | | | |

There will be no change in fit, function, quality or reliability of the product.


 $\label{eq:max-eyrh-Straße} \begin{array}{l} \text{Max-Eyth-Straße 1} \cdot 74638 \, \text{Waldenburg} \cdot \text{Germany} \\ \text{Tel.} + 49 \, \text{(0)} \, 79 \, 42 \, 945 - 0 \cdot \text{Fax} + 49 \, \text{(0)} \, 79 \, 42 \, 945 - 400 \\ \text{eiSos@we-online.de} \cdot \text{www.we-online.de} \end{array}$



DETAIL OF CHANGE:

BEFORE CHANGE

Straight gold contacts



Material PA66

AFTER CHANGE

R-shape gold contacts




Material: PA66

Material: PBT



R-shape gold contacts

Material: PA66



R-shape gold contacts

$$\label{eq:max-ey} \begin{split} \text{Max-Eyth-Straße 1} & \cdot \text{74638 Waldenburg} \cdot \text{Germany} \\ \text{Tel.} & +49 (0) \, 79 \, 42 \, 945 \cdot 0 \cdot \text{Fax} \\ & +49 (0) \, 79 \, 42 \, 945 \cdot 400 \\ \text{eiSos@we-online.de} & \cdot \text{www.we-online.de} \end{split}$$









Affected part numbers:

| 1 | | | | | | |
|---|-------------|-------------|--------------|-------------|-------------|--------------|
| | 7499010211A | 74990112121 | 7499011212A | 74990100013 | 74990100040 | 7499010004A |
| | 74990101211 | 7499011002A | 74990110031 | 7499011003A | 74990111211 | 74990111215A |
| | 7499011121A | 7499011122A | 74990112111A | 74990112123 | 7499011215A | 7499011216A |
| | 7499011222A | 7499110122 | 7499111001A | 7499111121A | 7499111440A | 7499111441A |
| | 7499111446 | 74992101211 | 7499210213 | 7499211002A | 7499211122A | 7499211123A |
| | 7499410213 | S16100001 | S16100013 | S17100003 | S17100055 | 7499011121 |
| | 7499011125 | 74990112120 | 7499011215 | 7499210121 | 7499210122 | 7499210211 |
| | 7499211121 | 7499010213 | 74990112124 | 7499011213A | 7499011223A | 7499111213 |
| | 7499111423 | 7499111424 | 7499211220 | S14100074 | 7499010441 | 7499210121A |
| | 74992111211 | 7499211121A | 7499211230 | 7499211260 | 7499410420 | 7499011001A |
| | 7499011444A | S13100040 | S16100099 | S17100096 | S14100137 | S18100064 |
| | 7499012000 | | | | | |
| ı | | | | | | |

$$\label{eq:max-ey} \begin{split} \text{Max-Eyth-Straße 1} & \cdot \text{74638 Waldenburg} \cdot \text{Germany} \\ \text{Tel.} & +49 \text{ (0)} \text{ 79} \text{ 42} \text{ 945-0} \cdot \text{Fax} \text{ +49 (0)} \text{ 79} \text{ 42} \text{ 945-400} \\ \text{eiSos@we-online.de} & \cdot \text{www.we-online.de} \end{split}$$



RELIABILITY / QUALIFICATION SUMMARY:

As the material as well as the R-shape gold contacts are already used in other articles of the series, no additional tests are needed and the change is released by Product Management Department.