


FineAdjust Applicator

Application Tooling Specification Sheet



Order No. 63902-9000

# FEATURES


- Directly adapts to most automatic wire processing machines
- Quick punch removal with the push of a button for fast and easy tooling change
- Applicator designed to industry standard mounting and shut height 135.80mm (5.346")
- Quick set-up time; plus the crimp height, track and feed adjustments can be set without removing the applicator from the press
- Fine adjustment allows users to achieve target with little effort by adjusting in increments of .015mm (.0006") for conductor crimp height and .063mm (.0025") for insulation height
- Independent adjustment rings allow users to quickly adjust the conductor or insulation crimp height without affecting each other

# SCOPE

Products: Right Angle, 2.00mm (.079") Board-In Terminal for 24-30 AWG.

Terminal Series No.	Terminal Order No.		Wire Size		Insulation Dian	Strip Length		
Terminal Series No. Terminal Order No.		AWG	mm²	mm	In.	mm	In.	
	35021-1201	35021-1310						
35021	35021-1300	35021-1360	24-30	0.20-0.05	1.50	.059	1.80-2.20	.071087
	35021-1301							





### **CRIMP SPECIFICATION**

Terminal Series No.	Bell n	nouth	Cut-off Tab	Maximum	Conductor Brush	
	mm	ln.	mm	ln.	mm	ln.
35021	0.20-0.50	.008020	0.30	.012	0.0-1.0	0.0039

	Bend up Bend down				Punch Width mm (Ref)				Seam
Terminal Series No.					Conductor		Insulation		
	Degree		Degree		mm	In	mm	In	Seam shall not be open
35021	3	3	3	3	1.20	.047	1.60	.063	and no wire allowed out of the crimping area

After crimping, the conductor profile should measure the following.

	Wire Size		Conductor					
Terminal Series No.			Crimp	Height	Crimp Width (Ref)			
	AWG	mm2	mm	In.	mm	In.		
	24	0.20	0.75-0.80	.030032	1.22	.048		
35021	26	0.13	0.75-0.80	.030032	1.22	.048		
550Z I	28	0.08	0.68-0.73	.027029	1.22	.048		
	30	0.05	0.65-0.70	.026028	1.22	.048		


	Wire Size			Insula	Pull Force Minimum			
Terminal Series No.			Crimp Height (Ref)				Crimp Width (Ref)	
	AWG	mm2	mm	In.	mm	In.	Ν	Lb.
35021	24	0.20	1.50	.059	1.70	.067	29.4	6.60
	26	0.13	1.45	.057	1.70	.067	19.6	4.40
	28	0.08	1.40	.055	1.70	.067	9.8	2.20
	30	0.05	1.35	.053	1.70	.067	4.9	1.10

#### **Tool Qualification Notes:**

- 1. Pull Force should be measured with no influence from the insulation crimp.
- 2. The above specifications are guidelines to an optimum crimp.

# PARTS LIST

	FineAdjust Applicator 63902-9000									
Item	Order No	Engineering No.	Description	Quantity						
	Perishable Tooling									
	63902-9070	63902-9070	Tool Kit (All "Y" Items)	REF						
1	63863-2002	63863-2002	Conductor Punch	1 Y						
2	63445-1213	63445-1213	Conductor Anvil	1 Y						
3	63863-2003	63863-2003	Insulation Punch	1 Y						
4	63445-1615	63445-1615	Insulation Anvil	1 Y						
5	63443-0003	63443-0003	Cut-Off Plunger	1 Y						
6	63443-0012	63443-0012	Front Plunger Retainer	1 Y						
		Other Co	omponents							
7	11-18-4083	60707-8	Feed Guide	1						
8	11-24-1067	4996-4	Cut-off Plunger Spring	1						
9	11-40-4039	8302-5	Front Plunger Striker	1						
10	63443-0009	63443-0009	Scrape Chute	1						
11	63443-0024	63443-0024	Lower Tooling Key	1						
12	63443-1703	63443-1703	17.30mm (Height Spacer)	1						
13	63443-2215	63443-2215	15.00mm (Coarse Spacer)	1						
14	63443-2312	63443-2312	3.60mm (Fine Spacer)	1						
15	63443-0090	63443-0090	Wire Stop	1						
16	63443-6109	63443-6109	Rear Cover	1						
17	63445-1613	63445-1613	Spacer Anvil	1						
	Frame									
18	63800-4901	63800-4901	Тор	1						
19	63801-3281	63801-3281	Base	1						
20	63801-4650	63801-4650	Track	1						
		Hard	dware							
21	N/A	N/A	M3 by 6 Long SHCS	2**						
22	N/A	N/A	M3 by 6 Long FHCS	1**						
23	N/A	N/A	M4 by 6 Long SHCS	2**						
24	N/A	N/A	M4 by 12 Long BHCS	2**						
25	N/A	N/A	M4 by 45 Long SHCS	2**						
26	N/A	N/A	M5 by 12 Long SHCS	1**						
27	N/A	N/A	#10-32 by 3/8"Long Flat SSS	1**						
28	N/A	N/A	#10-32 Hex Jam Nut	1**						
** A	** Available from an industrial supply company such as MSC (1-800-645-7270).									



## NOTES

- 1. Molex recommends an extra perishable tooling kit be maintained at your facility.
- 2. Verify tooling alignment by manually cycling the press and Applicator before crimping under power. Check that all screws are tight.
- 3. Slugs, Terminals, Dirt and Oil should be kept clear of work area.
- 4. Wear safety glasses at all times.
- 5. For recommended maintenance refer to the FineAdjust Manual.

**CAUTION**: This applicator should only be used in a press with a shut height of 135.8mm (5.346"). Tooling damage could result at a lower setting.

**CAUTION**: To prevent injury never operate this Applicator without the guards supplied with the press or wireprocessing machine in place. Reference the press or wire processing manufacturer's instruction manual.

CAUTION: Molex crimp specifications are valid only when used with Molex terminals, applicators and tooling.

Visit our Web site at http://www.molex.com